



Firmware Release Notes

Version 1.10

[27-05-2016]

Project Number: HE 100925

Product Description: NCC-1222

For this version you need MIB1_6 or higher to work properly with TRAPS.

Technetix Ltd

Communications House, Edward Way, Burgess Hill, West Sussex RH15 9TZ, UK

Kazemat 5, NL-3905 NR, PO Box 385, NL-3900 AJ, Veenendaal, Netherlands

Technetix Ltd.	Class	Company Confidential	Doc No.	HE 100925 xx
	Title	FW Release Notes for NCC-1222 V1.10	Issue	0A
Page 1 of 2	Author	G. Bronkhorst	Date	27-05-2016

Bug fix(es):

- Fixed Static IP address after upgrading was locked for changes. In DHCP mode it was not locked. We unlocked changes now also for Static IP addresses.

New Feature(s):

- Added feature to copy NCI setting to other NCI modules in a rack. The copy function is based on copy one to many.

Caution conditions:

- With installing this new firmware version, it's always better to reset the NCC-1222 with a Factory Default.
- The HEX switch on the RPS-UNI **MUST** match with the installed power supplies to get correct overcurrent warnings. There is not control line between the NCC-RPS to monitor if the HEX switch is correctly set by the technician because of short in hardware lines.
- When the Session on the Website is not saved or restored before the website is closed, the last position will stay active till:
 - 1. Reboot of NCC-1222**
 - 2. Reopening the specific configuration Website address. When readout of the SNMP value is equal to the actual state or the last Website situation. Always press Save or Restore after closing the Web session. This can't be overruled automatically since Web is only a readout and not a host.**

Technetix Ltd.	Class	Company Confidential	Doc No.	HE 100925 xx
	Title	FW Release Notes for NCC-1222 V1.10	Issue	0A
Page 2 of 2	Author	G. Bronkhorst	Date	27-05-2016